

FIG.	PART NO.	DESCRIPTION OF PART	NO. REQ.	
1		CP Service Nameplate	(1)	
2	10-15-0965	CP Warning Label	(1)	
3	10-20-8925	CP HIGH OUTPUT Warning Label (for 48-11-2425 battery only)	(1)	
4	12-20-2498	XC Service Nameplate	(1)	

## FIG. NOTES

2,3,4

A clean, dry surface is essential for proper performance for any adhesive system. The area intended for application of any adhesive label or nameplate must be prepared by cleaning with isopropyl alcohol. The solvent is to be applied with a clean, lint free applicator and the surface allowed to dry before applying the label or nameplate.